5-63 EDITIONS	1 2 m			MFG. 9-66
ېر Apı	proved For Telear	CLASSIFIED MESSAGE se 2002/05/06 : CIA-RDPG(B0004 80009000	306824NG
DATE	proved refraction	50 2002/00/00 : Oi/ (1 120	
ràvie.		SECRET	2	10 10
	A.		3	11
	R	CHILAG	4 5	12
TO :		INIT ACT INFO	6	114
•	CHIEF		7	15
FROM :	D'CHIEF	- - -	8	16
A many only b	OPS -			
ACTION:			i i	
kro	PLANS			
NFO :				
	HOLD FOR:			
	T.H.	0 2/	ı	
IN 75405	FILE	19 hs	41-20 V	
10 25V1A	in rec			
	INFO	<u> </u>	CITE	
SECRET 2				
SECRET2 1A		<u> </u>		
SECRET 2		<u> </u>		
SECRET2 1A IMMEDIATE OXCART MAT		<u> </u>		
SECRET2 1A IMMEDIATE OXCART MAT 1A		<u> </u>		
SECRET2 1A IMMEDIATE OXCART MAT		<u> </u>		
SECRET2 1A IMMEDIATE OXCART MAT 1A REF A		<u> </u>		
1A IMMEDIATE OXCART MAT		<u> </u>		
SECRET2 1A IMMEDIATE OXCART MAT 1A REF A X1A B		840		
SECRET2 1A IMMEDIATE OXCART MAT 1A REF A		840		

A GRADUAL BUILD-UP OF ERROR THROUGHOUT ENTIRE FLIGHT. AFTER FINDING NO DISCREPANCIES IN THE COMPUTER EXTRACTED DATA, THE CONCLUSION REACHED WAS A FAULT IN THE "Y" GYRO LOOP. A FUNCTIONAL TEST TO VERIFY THIS DIFFICULTY WAS BEGUN ON 5-23-67. DURING THE PERFORMANCE OF TESTS, THE NBR 3 INVERTER WAS INADVERTENTLY SHUT OFF CAUSING THE COMPUTER DRUM TO RUNDOWN. THIS NECESSITATED REMOVAL OF THE SYSTEM AND ERASING THE DRUM. BECAUSE OF THE STRONG POSSIBILITY THAT THE PROBLEM WAS CAUSED BY A FAULTY GYRO AND THE NECESSITY OF INSTALLING AN OPERATIVE INS FOR FLIGHT SCHEDULE, WE ELECTED TO REPLACE THE SYSTEM AND RETURN THE ORIGINAL TO AREA FOR TROUBLESHOOTING AND REPAIR Approved For Release 2002/05/06 CIA-RDP69B00041 MOUTHWINTHOOD-4

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. COPY NO.

Approved For Release 2002/05/06 : CIA-RDP69B0004TR001900030002-4	
IN: 75405 SECRET PAGE 2	
A. DURING PRE-INSTALLATION CHECKS OF VI31 ON 5-24-67 A	
COMPUTER VGN SHORT TO AIRCRAFT SKIN WAS FOUND IN ARTICLE WIRING.	
SINCE THIS IS A POSSIBLE CAUSE OF THE ERRORS ENCOUNTERED ON THIS	
FLIGHT, THE SYSTEM WILL BE RETAINED AT KADENA FOR INVESTIGATION	
AND POSSIBLE USE.	
2. H8-J7, THE REMAINING INS SYSTEM AT KADENA CONTINUES TO	
EXHIBIT ACCELEROMETER LEVELING PROBLEMS IN THE LAB AND IS UNDERGOIN	G
TROUBLESHOOTING. BECAUSE OF THE LACK OF IMMEDIATE SPARES, IT STILL	
REQUESTED THAT THE RWARD A KNOWN GOOD INS IF AVAILABLE WITHOUT	UI
AFFECTING DEPLOYMENT. 25X1A	
3. IF TELECON REQUESTED PER 1087 STILL DESIRED - PLEASE	
ADVISE.	

TOR: 250015Z MAY 67

SECRET